



Become aware of Problem  Customer <input checked="" type="checkbox"/>		Date : 23-Jul-2025  Ref: REHLKO-20250720-184329-79	
Name of Customer/ Vendor / Dept : Infineum			
<b>Problem</b>			
Fuel leakage			
<b>Discipline 1 Use Team Approach</b>		Date : 23-Jul-25	
		Contact	Telephone
Team Leader	Kelvin	thetminhein232377@gmail.com	91445084 (Mobile)
Champion	Champion	champion@gmail.com	
Members	Robert Leow	robertleow@icloud.com	+6597235662 (Mobile)
<b>Discipline 2 Describe the Problem</b>			Date : 23-Jul-2025
			Fuel leakage
<b>Discipline 3 Implement and Verify Containment Action</b>			Date : 23-Jul-2025
Action	Who	When	Status
cross thread	Kelvin	01-Jan-70	Complete
<b>Discipline 4 Problem Analysis</b>			Date : 23-Jul-2025
cross thread			

<b>Discipline 5 Corrective Action Plan</b>		Date : 23-Jul-2025	
Action	Who	When	Status
No corrective actions recorded.			
<b>Discipline 6 Verify the Effectiveness of Corrective Action</b>		Date : 23-Jul-2025	
Action	Who	When	Status
solved	Kelvin	01-Jan-70	Complete
<b>Discipline 7 Preventive Recurrence</b>		Date : 23-Jul-2025	
Action	Who	When	Status
quality	Kelvin	01-Jan-70	Complete
Prepared By - N/A Date - 23-Jul-25	Approved By - N/A Date - 23-Jul-25		