

Become aware of Problem Customer <input checked="" type="checkbox"/>		Date : 24-Jul-2025 Ref: REHLKO-20250723-205456-6B	
Name of Customer/ Vendor / Dept : Infineum Problem			
Fuel leakage			
Discipline 1 Use Team Approach		Date : 24-Jul-25	
		Contact	Telephone
Team Leader	Kelvin	thetminhein232377@gmail.com	91445084 (Mobile)
Champion	Champion	champion@gmail.com	
Members	Robert Leow	robertleow@icloud.com	+6597235662 (Mobile)
Discipline 2 Describe the Problem			Date : 24-Jul-2025
			Fuel leakage
Discipline 3 Implement and Verify Containment Action			Date : 24-Jul-2025
Action	Who	When	Status
cross thread	Kelvin	01-Jan-70	Complete
Discipline 4 Problem Analysis			Date : 24-Jul-2025
cross thread			No image.
Discipline 5 Corrective Action Plan			Date : 24-Jul-2025
Action	Who	When	Status
No corrective actions recorded.			
Discipline 6 Verify the Effectiveness of Corrective Action			Date : 24-Jul-2025
Action	Who	When	Status
good	Kelvin	01-Jan-70	Complete
Discipline 7 Preventive Recurrence			Date : 24-Jul-2025
Action	Who	When	Status
alart to operation team	Kelvin	01-Jan-70	Complete
Prepared By - N/A	Approved By - N/A		
Date - 24-Jul-25	Date - 24-Jul-25		